Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Cost	Deferred	Approved
A. I HEREBY ACKNOWLEDGE THAT I HAVE REMOVED ANY FIREARMS AND/OR PERSONAL ITEMS FROM MY VEHICLE. I ALSO AGREE THAT BRUMOS MOTOR CARS INC. WILL NOT BE RESPONSIBLE FOR ANY ARTICLES LEFT IN MY VEHICLE WHILE AT BRUMOS MOTOR CARS INC._____		$0.00		X
B. CUSTOMER STATES HARD TO GET INTO 1ST AND REVERSE PLEASE ADVISE		$129.95		X
Replace clutch master and slave cylinder then bleed to start. Remove improperly installed clutch line between master and slave cylinder and reinstall correctly so that it does not rub on rear suspension. (Clutch pedal does not have a full stroke. Found sign of master cylinder leaking. Currently unable to drive vehicle and check clutch pedal engaugment to get an idea of the condition of clutch. Found clutch line rubbing on RR suspension.)	Fail	$1,805.18		
C. CUSTOMER STATES CHECK ENGINE LIGHT CAME ON SATURDAY ON HIS WAY INTO DEALERSHIP		$129.95		X
Replace Oil separator, accordian hose, oil fill tube, coil packs, spark plugs and air flow meter/sensor(unknown sensor manufacture or part number). Program DME and perform road tests (The engine is misfiring and fuel trim adjustment is maxed out. Oil separator and accordion hose are allowing un-metered air into the engine. Oil fill tube may have a crack in it as well. Found coil packs have cracks. Spark plug tips are worn.)	Fail	$2,653.25		
D. CUSTOMER STATES VEHICLE IS IDLING VERY HIG PLEASE ADVISE		$32.49		X
Replace idle air control valve with new gasket. (Idle air control valve is sticking, has cracks in housing and did not have a gasket between it and the throttle body.)	Fail	$733.58		
E. BRUMOS PORSCHE COURTESY INSPECTION		$0.00		X
Remove control unit and inspect fuse and circuit board (Key remote is not functioning. May need new key head remotes. Condition of control unit unknown.)	Fail	$194.93		
Replace Ignition switch and transfer key tumbler to new housing (Ignition switch is sticking)	Caution	$621.86		