



Original Customer Requests	Status	Cost	Deferred	Approved
Replace driver window regulator. (Driver window making crunchy sound when window is rolled up or down)	Caution	\$796.63		
Recover freon from A/C system. Remove dash to access and remove HVAC box. Take apart HVAC, remove blend doors clean foam and install new foam on blend doors. Charge A/C system with new freon. (Foam coming from dash vents. Foam is off of Blend doors inside HVAC box)	Caution	\$2,251.16		
F. PERFORM CAR WASH AND VACUUM - \$25.95 NO CHARGE TO CUSTOMER - SUBJECT TO AVAILABILITY OF WASH TECHNICIAN AND PREVAILING WEATHER CONDITIONS				X
Inspection Recommendations	Status	Cost	Deferred	Approved
Replace coolant tank (Found coolant level to be low)	Fail	\$1,455.02		
Diagnose horn problem (Found horn to be inoperative)	Fail	\$129.95		
Diagnose engine oil leak (Found engine oil seep)	Caution	\$202.88		See AI-18
Replace serpentine belt and pulleys (Found serpentine belt in poor condition)	Caution	\$717.85		See AI-20
Replace left side headlight assembly (Found broken/cracked right side headlight assembly)	Caution	\$1,237.99		See AI-55
Replace right side headlight assembly (Found broken/cracked right side headlight assembly)	Caution	\$1,237.99		See AI-55
Totals, Taxes and Fees		Cost	Deferred	Approved
Estimate Subtotal		\$14,330.6	\$0.00	\$292.39
Shop supplies		\$28.00		\$28.00
Tax		\$1,005.10		\$22.43
Estimate Total		\$15,363.7		\$342.81
For "See AI-" items  see the "Additional Information" section 				

Vehicle Information

Item	Description
Year	1999
Make	Porsche
Model	Boxster
Submodel	Base
Engine	2.5L H6 DOHC (MFI)